# **E960 TURBINE**





# **E960 Turbine system**






E960 A E960 B


# **Prepare the work**

- Hard copies
- Tolerances
- Assemble brackets
- Battery status
- Clean measurement points




#### **Assemble the laser transmitter**

• Using support beam



#### **Assemble the Laser transmitter**




Mount the laser transmitter

#### **Assemble the Laser transmitter**


• Using vertical support beam




#### **Assemble the Laser transmitter**



### **Assemble the detector**




### **Assemble the detector**



### **Assemble the detector**

Using sliding bracket




#### **Check the environment**

- Temperature
- Sunlight
- Airflow
- Vibrations
- Rain
- Mobile phone
- Clean




#### Check the environment

- Magnets are seated a machined surface, without tension.
- All magnets have full contact with the surface. If not, release and tighten screws.
- All screws on the bracket are properly tightened (but do not overtighten).
- Make sure that the laser transmitter battery is replaced to avoid interrupting the measurement.



# Rough align laser beam

• Use the visual targets to prealign laser beam.




#### Mount the detector


• Select a horizontal support beam and extensions, long enough to rest on both sides with good margin.




# Align laser beam



- 1. Place detector probe at 9 o'clock.
- 2. Select 0




- 3. Turn to 3 o'clock
- and select 1/2 5. Adjust horizontal error to 0.00




- 6. Turn to 6 o'clock.
- 4. Adjust vertical error to 0.00

## Adjust measurement probe

- 1. Turn the probe to position 6 o'clock.
- 2. Adjust the detector vertically and horizontally to the centre of the laser beam.
- 3. Adjust the detector fixture so that the probe runs parallel to the surface to be measured.





Green line = correct

## Measure




#### Measure

• Measure using Half circle or Multipoints.




Values are registered at three positions in a half bore.



#### Measure with or without inclinometer




With inclinometer



Toggle button to toggle inclinometer on/off

#### Measure

• Face the laser transmitter from the detector. Then 9 o'clock is to the left, as in the measuring programs.



#### Result



